

DMR Copy of Record

Permit

Permit #:
Major:

MAR054014
No

Permittee:
Permittee Address:

Boston Concrete Corporation
706 Broadway Street
Lowell, MA 01854

Facility:
Facility Location:

BOSTON CONCRETE CORPORATION
706 BROADWAY STREET
LOWELL, MA 01854

Permitted Feature:

001
External Outfall

Discharge:

001-E2
Concrete and Gypsum Product Manufacturers

Report Dates & Status

Monitoring Period:
From 10/01/18 to 12/31/18

DMR Due Date:
02/28/19

Status:
NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name:
Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI: --

| Parameter | | Monitoring Location | Season # | Param. NODI | | Quantity or Loading | | | | | Quality or Concentration | | | | | | # of Ex. | Frequency of Analysis | Sample Type | |
|-----------|-------------------------|---------------------|----------|-------------|------------------------|---------------------|---------|-------------|---------|-------|--------------------------|---------|-------------|---------|-------------|-------------|-----------|-----------------------|-------------------|-----------|
| Code | Name | | | | | Qualifier 1 | Value 1 | Qualifier 2 | Value 2 | Units | Qualifier 1 | Value 1 | Qualifier 2 | Value 2 | Qualifier 3 | Value 3 | Units | | | |
| X00530 | Solids, total suspended | 1 - Effluent Gross | 0 | -- | Sample | | | | | | | | | | = | 970 | 19 - mg/L | | 01/90 - Quarterly | GR - GRAB |
| | | | | | Permit Req. Value NODI | | | | | | | | | | <= | 100 MAXIMUM | 19 - mg/L | | 01/90 - Quarterly | GR - GRAB |
| | | | | | | | | | | | | | | | | | | | | |
| X01045 | Iron, total [as Fe] | 1 - Effluent Gross | 0 | -- | Sample | | | | | | | | | | = | 24 | 19 - mg/L | | 01/90 - Quarterly | GR - GRAB |
| | | | | | Permit Req. Value NODI | | | | | | | | | | <= | 1 MAXIMUM | 19 - mg/L | | 01/90 - Quarterly | GR - GRAB |
| | | | | | | | | | | | | | | | | | | | | |

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

| Parameter | | Monitoring Location | Field | Type | Description | Acknowledge |
|-----------|-------------------------|---------------------|---|------|--|-------------|
| Code | Name | | | | | |
| 00530 | Solids, total suspended | 1 - Effluent Gross | Quality or Concentration Sample Value 3 | Soft | The provided sample value is outside the permit limit. (Error Code: 1) | Yes |
| 01045 | Iron, total [as Fe] | 1 - Effluent Gross | Quality or Concentration Sample Value 3 | Soft | The provided sample value is outside the permit limit. (Error Code: 1) | Yes |

Comments

Attachments

| Name | Type | Size |
|--------------------------|------|---------|
| BostonConcrete2018Q4.pdf | pdf | 1479013 |

Report Last Saved By

Boston Concrete Corporation

User:
Name:
E-Mail:
Date/Time:

MAR1000L3
MaryEllen Doherty
mdoherty@sakenvironmental.com
2019-01-10 11:00 (Time Zone: -05:00)

Report Last Signed By

User:
Name:
E-Mail:
Date/Time:

DTHEBEARGE
David Thebearge
dthebearge@bostonconcrete.com
2019-01-10 11:02 (Time Zone: -05:00)